

BUILDING SAFETY CERTIFICATENo. EE/R&B/NLG/CB/D2/25Dated: 10.07.2025

It is certified that the existing building

SR PRIME SCHOOL - 9-18-70 chaelapally, Nalgonda (Address) is having block(s)/floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2	G+3				

The building is owned/occupied by

SR PRIME SCHOOL - SARVAHITHA EDUCATIONAL SOCIETY (Committee Educational

Society) (Name of the Institution) and has complied with the Building safety requirements in accordance with

National Building Code Rules, and verified by the officers concerned of (R&B) ROADS & BUILDINGS (Name ofDepartment/Govt.) on 10.07.25 (date of inspection) in the presence ofA. SANTHOSH REDDY (Secretary) (Name and address of the Manager/Secretary or his representative)and that the building/premises is fit for occupancy for running school with effect from 10.07.25 for a period of ONE years in accordance with rules and subject to compliance of the specific conditions as appended:

1. North:- Land of Others
2. East:- 33 feet wide Road
3. West:- Remaining property of Lessor out of House no: 9-18-70
4. South:- Road and Land of Others.

Issued on 10.07.2025 at Chaelapally by

(Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail)

Signature with Seal: Md. MahamoodName: MD. MAHAMOODDesignation: Asst. EngineerName & Address of Department/Office: Assistant Engineer(R&B) Buildings Section-1NALGONDA.